

subject to

22 JUN 1962

4E

ved by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

P'S NAME.....

M.V. 'CENTRAL' CO<sup>4</sup>

REPORT

lio

No. 8408

Allegations

The windlass renewed but not examined working;  
the Surveyor recommends that the windlass is examined  
under working conditions at earliest opportunity.

~~C.S. Advanced.~~

It is submitted that this  
vessel is eligible to remain  
as **CLASSED**, subject as not recommended.

by  
22/6/62



© 2021

Lloyd's Register  
Foundation

012741-012745-012744