

COPY

Kobe Rpt. 9

No.

14746

## LLOYD'S REGISTER OF SHIPPING



No. B1-120830

Port

KOBÉ

2nd August, 1965.

**This is to Certify** that I have surveyed part of the machinery of the s.s. "BONNA", 6,910 Gross tons of Panama for Main Boiler Survey, condition of class to main sea inlet valve and Dry docking whilst the vessel lying in drydock and afloat at Nagoya on the 27th July, 1965 and subsequently

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned MBS 7.65, subject to main sea inlet valve being specially examined at next drydocking and to any outstanding condition of class being dealt with as previously recommended.

Parts now examined:—

Port & starboard main boilers in their entirety together with their mountings.  
 Safety valves of port & starboard main boilers adjusted under steam.  
 Oil fuel burning system and remote controls examined in accordance with rule.  
 Main sea inlet valve.  
 Propeller, aft end of stern bush and outside fastenings of sea connections (Wear down of stern bush 4.0mm).

*S. Matsumoto*  
 Surveyor to Lloyd's Register of Shipping  
 S. Matsumoto

## KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey  
 CSM Continuous Survey of Machinery  
 DBS Donkey Boiler Survey  
 ES Engine Special Survey

MBS Main Boiler Survey  
 OF Fitted for oil fuel (date) EP above 1500P  
 SGS Steam Generator Survey  
 SPS Steampipe Survey

TS Tailshaft Survey  
 TS (CL) Tailshaft Survey—Continuous Liner  
 TSN Tailshaft renewed  
 TS (OG) Tailshaft Survey—Oil Gland

SM/rm

This Certificate is issued upon the terms of the Rules and Regulations of the Society which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."