

Lloyd's Register of Shipping.

BONNA

Ship's Name S.S. "SALT LAKE PARK" ~~WAIRUNA~~ Official No. ~~175392~~

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in May, 1944.

Alterations:-

Port Side:- D.E.M.S. accommodation forward of No. 19 bulkhead in No. 5 tween deck removed together with five ventilators (one-20" dia., one-12" dia., and three-6" dia.) on upper deck, nine port lights and two storm valves in way. Openings efficiently closed with welded spigot plates. Bulkhead extended to ship's side with required stiffeners.

Starboard Side:- One room removed necessitating moving bulkhead aft four frame spaces. One 2'-0" dia. escape hatch on upper deck and two port lights in way removed and openings closed with welded spigot plates.

Forward Magazine in No. 1 tween deck removed together with access trunkway and hinged steel door. Two-10" dia. ventilators removed and deck apertures efficiently closed with welded plates. Fore and aft girder extended to collision bulkhead with bulb angle stiffening.

All new work satisfactorily hose tested on completion.

D. J. Ambled

Surveyor to Lloyd's Register
Vancouver, B.C.

9th November, 1945.

*ML:
1812-45*

[Handwritten mark]

[Large handwritten signature]



© 2021

Lloyd's Register Foundation

012 722-01277-0247