

# LLOYD'S REGISTER OF SHIPPING

FOUNDED 1760

RE-CONSTITUTED 1834

## LLOYD'S MACHINERY CERTIFICATE (LMC)

This is to Certify that the Machinery of the

Twin Screw Motor Tanker "STANVAC JURONG"

690 Tons, of Singapore

has been Specially Surveyed by the Surveyors to this Society during construction at Kobe

and was reported to be on the 14th November 1959 at Mukaishima in good working condition.

The Record ✕ LMC has been made in the Register Book, subject to Periodical Surveys as required by the Rules.

### PARTICULARS

Description of Machinery	2 Oil Engines 4 Stroke Cycle Single Acting through clutches to two screwshafts.	
Makers of Main Engines	Nippon Hatsudoki Co.Ltd.	
Makers of Main Boilers	-	
Approved pressure of Main Boilers	-	lb. per square inch saturated steam
	-	lb. per square inch superheated steam
Steam Temperature	-	
Approved pressure of Aux./Donkey Boilers	-	lb. per square inch
Approved pressure of Steam Heated Steam Generators	-	lb. per square inch
Approved total	B.H.P. 1040	350 r.p.m. of Engine
	S.H.P. -	350 r.p.m. of Propeller
<p>With the propeller clutch engaged the main engine should not be operated above 350 RPM, nor run continuously between 205 RPM and 240 RPM, or between 290 RPM and 330 RPM. When the cargo pump clutch is engaged the main engine should be operated in the speed range between 330 RPM and 350 RPM only.</p>		

Witness my hand


*W. J. Ferguson*  
Secretary

*Herbert A. Bell*  
Chairman

71, Fenchurch Street, London, E.C.3. 26th February, 1960.

This Certificate is issued upon the terms of the Rules and Regulations of the Society to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register  
Foundation