

(Received at London Office)

Place 864-1 Mukaishimacho Mitsukigun Date May 22<sup>nd</sup> 1959  
Kirashima Japan

We request that the Committee of Lloyd's Register will instruct the  
Surveyors to Specially Survey during Construction the Hull, Engines and  
of the Vessel No. 478 building by Messrs. Mukaishima Dock  
Co. LTD for Messrs. Standard Vacuum Oil Co. LTD  
600 Tons. Length 54 m, Breadth 11 m, Depth 3.85 m  
to be Classed Harbour service A1

We undertake to arrange for every facility to be given to the Surveyors  
out the duty in question, and we agree to pay the fees for the Surveyor's  
in addition to the actual travelling and other expenses incurred by the  
rs in connection therewith.

This request is made upon the terms of the Rules and Regulations of  
Register of Shipping, which provide that:-

the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly  
it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances  
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any  
the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its  
es or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

tion from Engine Makers Nippon Hatsudoki Co. LTD  
e 24/6/59 Boiler Makers

Signature M. Sugihara

Secretary,  
Lloyd's Register of Shipping,  
71, Fenchurch Street, London, E.C.3.

oid misunderstanding, orders for materials requiring to be tested should be marked as follows:-  
"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

Is longitudinal traming fitted? (state where) \_\_\_\_\_ No  
Is strengthening for navigation in ice fitted? (state class) \_\_\_\_\_ No

EAD

te

4716

4717

4715

4718

© 2021

Lloyd's Register  
Foundation

0260-222216-827210

of floor

is duct keel