

Rpt. 9B

REPORT OF MACHINERY SURVEYS AND REPAIRS
FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Received London

26 JUL 1966

Ship's Name SS/MS ABEILLE N° 8

Port LE HAVRE

Processing
Number: LR 500088

Gross tons 252

Rpt. No. I0972

Port of Registry LE HAVRE

Date of
build 7/1946

Is there a rpt. 8? yes

No. of visits three

First date 15.6.66

Last date 30.6.66

Interim Cert. issued
& copy herewith? yes

Damage rpt. issued
& copy herewith? no

Last rpt. (H. Q. only)

Date of
completing rpt. 20.7.66

Surveyed at, if different from Port above

Is a rpt. 9A
attached? yes

MN

Nature of survey MBS-TS(OG)-DS

Survey fees

Damage fee

Expenses 20 Frs

TS(OG) 160 Frs
MBS 220 Frs

S.A. fee

BOILERS OPENED UP AND EXAMINED. (Identify by position and state condition and latest date of internal examination of each boiler, economiser or steam generator)

AUXILIARY, DONKEY or PRESS

(State if oil fired—OF
or exhaust gas—EG)

MAIN 15.6.66 - good

Air heaters

good

Superheaters

-

Safety valves

good

Mountings, doors
and fastenings

good

Safety valves
adjusted to { Sat
Spt

200 Lbs

Boiler securing
arrangements

good

Main economisers

Exhaust gas heated economisers
and their safety valves

Steam heated
steam generators

Steam generator or
E.G.E. safety valves adjusted to

Fired boiler forced
circulating pumps

Funnel, good

Have saturated steam pipes in cylindrical boiler
smoke boxes been examined as required by the Rules?

Were oil burning system &
remote controls examined
in accordance with Rules? yes - good

I declare that the items detailed in this report (except as stated otherwise) comply with the requirements of the Merchant Shipping (Cargo Ship Construction and Survey) Rules 1965, applicable to this ship, and are in all respects satisfactory for the service on which the ship is intended to ply, namely, International voyages/voyages within the limits

(The above declaration applies only to sea-going cargo ships
of 500 tons gross and above registered in the U.K.)

I recommend that the machinery of this ship remain as classed with ~~without~~ fresh record of MBS - 6/66 - TS(OG)
6/66- DS 6/66 - subject to any outstanding conditions of class
being dealtwith as previously recommended.

ALSO FOR

SRL FOR

TRO

NOTED BY
SRI
CESR

POSTING

HEADER

CERT

(Where conditions of class are recommended to be
retained, imposed, amended or deleted, particulars
must be stated above and on the interim certificate.)

Date of Committee

Minute

Surveyor to Lloyd's Register of Shipping
P.L.ROBERT, for A.MARECHAUX
and Self.

MONDAY 22 AUG 1966

As now
MBS. 6.66
TS. 6.66

Lloyd's Register
Foundation
012734-012743-0018

are to be cancelled; this need not be done when the machinery is
on a continuous survey basis. When any part has been hydraulic-
ally tested the pressure should be stated. Engine parts when referred
to by numbers should be cougled from forward.

that date a distinguishing mark thus: should be inserted against the
item and the circumstances and action taken or recommended
described fully under "defects and repairs". At part or complete
Special Surveys those items which are not applicable to the ship

The condition of any item is to be described as "good" only when
it has been examined, found or placed in good condition, and is
considered to be acceptable until the due date of the next Periodical
Examination. Where re-examination or repairs should be made before

EXAMINATION AND TESTING OF STEAM PIPES (state material and test pressure and, if selected lengths, identify by position)

MAIN

AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler
smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a Generators		Generators & governors	
b Exciters			
c Air coolers		m Motors	
d Motors			
e Air coolers		n Switchboards & fittings	
f Control gear cables, etc.		o Circuit breakers	
g Insulation resistance		p Cables	
h Insulating oil test		q Insulation resistance	
i Overspeed governors		r Steering gear generators & motors	
j Magnetic couplings		s Navigation light indicators	
k Air gap			
l Spare gear			
u PASSENGER SHIPS Have the emergency source of power and its associated circuits and, where fitted, the temporary source of power and its automatic arrangements been tested?			
CARGO SHIPS Have the emergency source of power and its associated circuits been tested?			

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

Wear & tear.


Maintenance routine repair.

For S.R.L. appendix N° 18 :

Port side feed aper. permanently closed 6/65 to be examined at
each Main boiler survey now examined and found to continue
efficient.

It is recommended to the Committee that the above note be
continued in the Special Reasons List Appendix

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2021

Lloyd's Register
Foundation