

COPY  
LLOYD'S REGISTER OF SHIPPING

4157

Port FUSAN

7 March 1962

part of

This is to Certify that I have  
Surveyed /the Machinery of the n.v. "UN KYONG" 1049 tons gross of INCHON,  
on the 4 March 1962 and subsequently whilst the ship lay afloat at FUSAN,  
R. of KOREA, for advancement of the CS and Condition of Class

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will **Recommend** that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book  
CS (with date) when the Survey is completed

and that her Machinery Classification Record be continued in the Book,  
without Condition regarding renewal of the crankcase of the port auxiliary  
engine.

Parts now examined:

(C.S. Items only)

Port Auxiliary Engine in its entirety.  
Main Engine Stand-by Lub. oil supply pump  
(belt driven from port aux. engine).

J. WINN

*J. Winn*  
Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

|     |  |         |                                   |
|-----|--|---------|-----------------------------------|
| ABS | Auxiliary Boiler Survey                    | SGS     | Steam Generator Survey            |
| CS  | Continuous Survey of Engines               | SPS     | Steampipe Survey                  |
| DBS | Donkey Boiler Survey                       | TS      | Tailshaft Survey                  |
| ES  | Engine Special Survey                      | TS (CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey                         | TSN     | Tailshaft renewed                 |
| MES | Modified Survey of Oil Engines             | TS (OG) | Tailshaft Survey—Oil Gland        |
| OF  | Fitted for oil fuel (date) FP above 150°F. |         |                                   |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly recuted, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."