

COPY

# LLOYD'S REGISTER OF SHIPPING



Port..... LISBON

Date..... 3rd May, 1965.

**This is to Certify** *that I have surveyed part of the machinery of the* **m.v. "RICARDO MANUEL"** **873 gross tons** *of* **PANAMA**  
*for* **Advancement of Continuous Survey Machinery and Tailshaft Survey on the 5th February 1965 and subsequently whilst vessel afloat and in dry dock**  
*and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned* **without fresh record subject to the tailshaft being renewed by 2/66 (12 months) and all other conditions of class being dealt with as previously recommended.**

Parts now examined:—

Main engine. ✓ All cyls, covers, pistons, valves and gears, gudgeons, connecting rods, crankpins and bearings.  
✓ Attached scavenge pump and compressor in entirety except journals and bearings.  
✓ Thrust blocks, shaft and bearings.  
✓ Intermediate shafts and bearings.  
✓ Crankcase doors.  
✓ Independent bilge pump.  
✓ Independent lubricating oil pump.  
✓ Clutch driven air compressor.  
✓ 125 kW diesel driven dynamo engine.  
✓ 25 kW diesel driven dynamo engine.  
✓ Propeller, fastenings, sea connections, tailshaft, stern tube, oil gland.

*W. Goodall*  
**W. Goodall**  
Surveyor to Lloyd's Register of Shipping

**MM.**

ABS Auxiliary Boiler Survey  
CSM Continuous Survey of Machinery  
DBS Donkey Boiler Survey  
ES Engine Special Survey

MBS  
OF  
SGS  
SPS

**KEY TO ABBREVIATIONS**

Main Boiler Survey  
Fitted for oil fuel (date) FP above 150° F.  
Steam Generator Survey  
Steampipe Survey

TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."