

Enclosures.

29th April, 1960

SOUTHAMPTON.

26065, 78, 95 - As recommended.

RMC 26085 - As recommended.

26025 "CAPETOWN CASTLE" - As recommended, except that a record of ABS 9,59 has been assigned.

26031 "SIREN" - This ship has today been classed #100A1 "Lighthouse Tender", together with the appropriate notations recommended by you. I shall be glad if you will confirm the diameter of the screwshaft at the top of the cone, as this is shown to be $7\frac{1}{2}$ " on the Approved Plan, but reported as $7\frac{1}{4}$ ". This information is also required for the sister ship "MERMAID", as requested in my Classing Letter of the 20th November, 1959.

I return the enclosed Forging Certificates for the intermediate and screwshaft which you should endorse as having been "Examined in the finished condition and found satisfactory". You should also forward the propeller Certificates and Forging Certificates for the thrust shafts, as these documents do not appear to have accompanied your reports.