

Ship's name

ESSO BALBOA

Port Newport News, Va. (9B) No. 8532

Last survey date

3/10/62

Class is subject to

None.

Repairs.

A superheater tube in S. boiler plugged and the
Surveyor recommends that the tube be removed al-
most MBS. This may be noted in the S.H. appendix.

Noted
as above.

14/11/62


~~ERL~~ - Appendix Note

Note for S.H. appendix

A Superheater tube plugged in
Starboard boiler.

✓

already posted
in PB
of spec. Surveyor
no remarks.



© 2021

Lloyd's Register
Foundation

012792 012793 0141