

COPY

LLOYD'S REGISTER OF SHIPPING



Port GIBRALTAR.

7th June, 1962.

This is to Certify that I have

Surveyed ^{part of} the Machinery of the Steam Tanker "ESSO NORWICH", 23,997 tons gross of London, whilst afloat, and at the Ship Repair Yard at Gibraltar, on the 4th June, 1962, and subsequently, during repairs to the No.5 Intermediate shaft bearing, and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel ~~the following Survey Records be made in the Supplement to the Register Book~~

~~and~~ that her Machinery Classification Record be continued in the Book.


without a fresh record of survey.

Parts now examined:

(C.S. Items only)

Main Engine No.5 Intermediate Shaft bearing

Bottom half remated.


W.F. Gromby. Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

| | | | |
|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey | SGS | Steam Generator Survey |
| CS | Continuous Survey of Engines | SPS | Steampipe Survey |
| DBS | Donkey Boiler Survey | TS | Tailshaft Survey |
| ES | Engine Special Survey | TS(CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey | TSN | Tailshaft renewed |
| MES | Modified Survey of Oil Engines | TS(OG) | Tailshaft Survey—Oil Gland |
| OF | Fitted for oil fuel (date) FP above 150°F. | | |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)

012792-012795-0147