

COPY

Ship's name "PADREWSKI" Port BDX No. 7089

Last survey date 19.10.62.

Class is subject to

15 fathoms of chain cable being supplied at the earliest opportunity and to permanent repairs to E.R. sea chest in No.6 D.B. tank (p.s) being permanently repaired next drydocking.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Repairs to E.R. sea chest in No.6 D.B. tank.

Recommendation

SUBJECT to 15 fathoms of chain cable being supplied at the earliest opportunity, without other conditions.

AS Now Subject
without.

IN S.R.L. APPENDIX
(Main structure partly of P.5 Steel).

C.S.S. Records Dept.
C.S.S.
to note. RECORDS
DEPT.

End. S.1

End. R

012796-012800-0128

Lloyd's Register
Foundation