

COPY

19 OCT 1962

Ship's name "PADAREWSKI"

Port GDK

No. 60

Last survey date 2.10.62

Ship is subject to

NONE

R.L. Appendix (as before or none) ~~XXXXXX~~

Structure of present survey (afloat and in drydock)

Temporary repairs to E.R. sea chest, (p.s).

Equipment: Damaged length of chain cable disconnected.

Recommendation

SUBJECT to 15 fathoms of chain cable being supplied at the earliest opportunity and to permanent repairs to E.R. sea chest in No.6 D.B. tank (p.s) being permanent repaired next drydocking.


As Now Subject.

IN S.R.D. APPENDIX.

(Main structure partly of P.5 Steel).



End. S.1



02796-012800-0136

Lloyd's Register
Foundation

(When
be retained
must be