

COPY.

# LLOYD'S REGISTER OF SHIPPING

RPT.No. 32674.-



Port BUENOS AIRES.-

28th. April 1961.-

**This is to Certify** *that I have*

*Surveyed the Machinery of the T.S.M.V. "HERNANDARIAS", (Yard No.106)  
1750 tons gross of Buenos Aires on the 2nd. July 1959 and subse-*

*quently on account installation of classed machinery. Vessel  
slipped and afloat at Yard of Messrs. ASTARSA Astilleros  
Argentinos Rio de La Plata S.A.*

*and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will Recommend that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book  
+ LMC.4, 61 and TS 4, 61.*

*and that her Machinery Classification Record be continued in the Book.  
"Engines not to be run continuously between 158 to 178 R.P.M."*

Parts now examined:

(C.S. Items only)

*A. F. Sinclair*

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

**A. F. Sinclair.-**

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, of the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.)

012796-012800-0205

Lloyd's Register  
Foundation