

TELEGRAMS: REGISTER KOBE.
TELEX: REGISTER KB6820

TELEPHONE: KOBE (3) 0141-0143



Lloyd's Register of Shipping.

7TH FLOOR, SHINKO BUILDING,
8, KAIGAN-DORI, IKUTA-KU,
(P. O. BOX NO. 446)
KOBE.

10-149

Your Ref:

Our Ref:

9th October, 1962.

Dear Sir,

LENKORAN

m.v. "LJUBOTIN"
Ishikawajima Yard No.593
Yokohama Report 4c No.4284

Referring to the above report it will be noted that there is no damper or detuner fitted to the auxiliary generator engine.

Unfortunately in the previous Yokohama reports covering yard Nos.591 and 592, it has been indicated that a detuner is fitted, this has been wrongly reported, and we would be glad if these reports Nos.4062 and 4191 could be corrected accordingly.

Regretting the inconvenience caused in this matter.

Yours faithfully,

592 LENKORAN
591 LSICHTANSK

Kate Merson
For the Surveyors.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

012818-012826-0027