

12 SEP 1963

Ship's Name SS/MS "LUCERNA".

Gross tons 11292

Is there a rpt. 8?

Port FALMOUTH Rpt. No. 14475.

No. of visits

First date

Last date

Interim Cert. issued
& copy herewith?Damage rpt. issued
& copy herewith?

Last rpt. (H.Q. only)

Date of
completing rpt.

Surveyed at, if different from Port above

Is a rpt. 9A
attached?

Yes.

MN

Nature of survey

Survey fees

Damage fee

Expenses

S.A. fee

DOCKING

Propeller Good. Sea connections Not examd. Oil gland None.

Fastenings Good.

Wear down of stern bush 7/64"

Has screw/tube
shaft been drawn?

No.

Date of examn.

Has shaft been
changed?

Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner?

Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS

(State if oil fired—OF
or exhaust gas—EG)

MAIN

P. & S. (OF & EG) Good.

Air heaters Good.

Superheaters -

Safety valves Good.

Mountings, doors
and fastenings Good.Safety valves { Sat 180 LBS.
adjusted to { Spt -Boiler securing
arrangements Good.

Main economisers

Exhaust gas heated economisers

Steam heated
steam generators

Steam generator safety valves adjusted to

Forced
circulating pumps

Funnel Good.

Have saturated steam pipes in cylindrical boiler
smoke boxes been examined as required by the Rules?Were oil burning system &
remote controls examined
in accordance with rules? Yes.

I recommend that the machinery of this ship remain as classed with/without fresh record of

Please see Report 9A.

(Where conditions of class are recommended to
be retained, imposed, amended or deleted, particulars
must be stated above and on the interim certificate.)

Date of Committee

Minute

WEDNESDAY 16 OCT 1963

See Rpt 9A

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register
Foundation

012827-012835-0241

At part or complete Special Surveys those items which are not applicable
to the ship are to be cancelled; this need not be done when the machinery is
on a continuous survey basis. When any part has been subjected to pressure
test this should be stated. Engine parts when referred to by numbers should
be counted from forward.considered that re-examination or repairs should
be made before that date a distinguishing mark
thereon should be inserted against the item and the
circumstances and action taken or recommended
described fully under "defects and repairs".The condition of any item is to be described as "good"
only when it has been examined, found or placed in
good condition, and is considered to be acceptable
until the due date of the next Periodical Examina-
tion. Where repairs have been effected or it is