

COPY

LLOYD'S REGISTER OF SHIPPING



Port.....of Piraeus,.....

.....3rd June, 1964.....

This is to Certify *that I have surveyed part of the machinery*

of the M.T. "AESOPOS" ex. "LUCERNA" 11292 *Gross tons* of Piraeus

for Docking Survey & Commencement of General Examination for postponement of Special Survey (c) due June, 1964 until June, 1965 as she lay afloat and in drydock at Syra on 6th and 7th May, 1964,

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following

survey records assigned
XXXXXXXXXXXXXXXXXXXX without fresh record of survey, subject to the inlet header of the M.E. jacket F.W. cooler and the discharge elbow on the General Service pump being renewed at earliest opportunity and to any other outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

For Docking Survey: Propeller.
Sea connections.
Underwater fastenings.

For General Examination: Main and auxiliary machinery examined under working condition.
Log books examined.
Electrical circuits megger tested.

To complete the General Examination, the Continuous Survey of Machinery cycle requires to be completed or advanced to include the M.E. No.5 crankshaft journal and bearing and the crankcase explosion relief devices.

J.C. Harrison

J.C. Harrison:

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."