

Ship's name

"
KEREM PE
"

Port

Istanbul

No.

5687

Last survey date

24.4.65

Class is subject to: - NIL.

The Surveyor reports damage to the port main boiler by lack of water and overheating on 18.4.65. The port furnace crown which was bulged has been part renewed and leaking tubes made tight. Repairs subsequently proved by hydraulic test!

It is submitted that this vessel is eligible to remain as CLASSED.

EDB

14.5.65



© 2021

Lloyd's Register
Foundation