

KINGSLAND

Special Survey Type 4 due 1.52

B.S. due 10.49

T.S. due 1.51

Outstanding damage on hull (10.48 Liv.)

Starboard side shell  
damage abreast No.2  
Hatch to be  
permanently repaired  
at Owners convenience.

Outstanding damage on machinery (2.49 Avm.)

Main condenser, 2 new  
water boxes and 2 new  
doors to be fitted.



© 2021

Lloyd's Register  
Foundation

012861-012867-0110