

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

*"SAN FRANCESCO"*Ship's Name *ex* "MERCIA"

Official No. _____

Port of Registry *Jonstorp Panama*This ship has been under survey at *Norrköping*on the 24th August, 1955 *195* and the following alterations to the conditions ofassignment of loadlines have now been ~~effected~~/found:—

The closing appliance of the forecastle bulkhead fitted with a strong hinged hardwood door $2\frac{1}{2}$ " thick, operated both sides. The door frame is fitted in the welded channels previously used for stormboards.

*Geo Smart**[Signature]**rd*
[Signature]

19 SEP 1955

A copy of this Report has been placed on board.



© 2021

Lloyd's Register
Foundation

012861-012867-0114