

19th February, 1962.

ROTTERDAM

53040, 48, 49, 50, 65, 68, 93, 96, 97, 116,
17, 29, 33, 34. As recommended.

RMC. 53139. As recommended.

53051. "EEMSHORN." As recommended. It is concluded that the stern bush oil-glands were found good but please confirm this.

53127. "CLYDEFIELD ." As recommended. Please state the stern bush wear down at all future periodical drydockings.

53090 "ANQUILA A." As recommended except that it is considered that the subject relating to the main engine No.1 lower water jacket can now be deleted from the Special Reasons List and noted in the SRL Appendix. In the circumstances please issue an amended Interim Certificate.

52843 "YESILIRMAK 2.")
52844 " 3.") The class #100A1 "Black Sea And Eastern Mediterranean Service" will be assigned upon receipt of reports of satisfactory examinations on the ships arrival in the service area.

In connection with your reports C.11 it is concluded that the scantlings of the machinery casings and superstructures are in accordance with approved plans.

Please state the type and area of the safety valves fitted on the boiler and whether easing gear is fitted.



© 2021

Lloyd's Register
Foundation

012875-012887-0227