

Depth of girder
Depth and thickness of Floor Plate)

4
15 1/2 5/2a ✓

SIDE KEELSONS, Number

Foremost "esc Mr. Moran"

Lon 10463

Representative of the Owners called in
in Office this afternoon & requested the
Entry Certificate

He was informed that the case had not
received the consideration of the Committee
that possibly she may be submitted to the Committee
now

The Owners representative stated he would
in again tomorrow afternoon.

The Southampton Surveyors request that the
certificate may be forwarded to them.

The fees are paid

I telephoned Southampton
they stated we could
issue certificate direct to
Owners. J. BAPDO

© 2021
Lloyd's Register
Foundation
012898-012906-0077

Bulb Angle, Plate, Tee Bulb, or Channel
Angle on upper edge

Angle on upper edge

Tie Plates