

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

28th September, 1962

Dear Sirs,

C
MWK/RW

CLASSING LETTER

10798. "EMILIE MAERSK" - As recommended, except that the Continuous Survey cycle has not yet been completed, and in the circumstances an amended Interim Certificate should be issued.

10641. ML (S) 813)
10643. ML (S) 815)

These ships have today been classed + 100 A1 "Burma Coasting Service" together with the appropriate notations recommended by you, subject to the hull distortion and deckhouse (leakage) being dealt with as necessary before commissioning.

10642. ML (S) 814

This ship has today been classed + 100 A1 "Burma Coasting Service" together with the appropriate notations recommended by you, subject to deckhouse (leakage) being dealt with as necessary before commissioning.

With regard to the above three ships, I have to inform you that when more than one ship is built from the same set of general plans, separate "As Built" plans of Midship Section and Profile and Decks must be sent for each ship. In this connection, I would refer you to Instructions to Surveyors, Part 2a, Para. 26.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
KOBE

Lloyd's Register
Foundation

012925-012932-0203