

MEMORANDUM

**From : LLOYD'S REGISTER OF SHIPPING,** 71, FENCHURCH STREET,  
LONDON, E.C.3.

(Ref. H.) R.

**To:** The Surveyor(s) at BANGKOK

**Date:** 28th June, 1962.

**Vessel's Name:** M.S. "FIONETTA"

113 JUL 1962

QUESTION

With reference to your letter of the 30th April, I shall be glad to learn whether you are able to advise me further regarding the verification of the equipment. Your confirmation that the screwshaft is fitted with a continuous liner is also desired.

*msb*

ANSWER

**Date:—** 7th July, 1962.

The Owners at Hongkong have been to again about the Certificates for the Anchor and Chains, but no answer has yet been received.

In my Report No. 2720 dated 3/5/62 and in my letter of 30th May, I have stated that the tailshaft now fitted has not got a continuous liner.

*D.C. Knott.*



Lloyd's Register  
Foundation

*13/7/62*  
*SPER*

012948-012453-0076

Note.  
~~Not for RB~~  
 delete ch. and insert *OK*  
 see Memo/ *16/7/62*



© 2021

Lloyd's Register  
Foundation