

COPY

Ship's name "M.H. THAMBIN"

Port DJA

No. 6335

Last survey date 30.1.65

Class is subject to

Repairs to cracked turbo blowers built-up  
seatings being reexamined by 1.65 (12 months)

---

The above subject of class  
now built with and recommended  
for deletion.

C.S. Advanced

It is suggested that this  
vessel is to remain

as CLASSED without subject

---

15.3  
estimated



© 2021

Lloyd's Register  
Foundation

012948-012953-0184