

Ship's name

"M.H. THAMRIN"

Port

KOB

No.

12417

2 MAR 1964

Last survey date 16.1.64.

Class is subject to

Repairs to cracked turbo blowers built-up
seatings, being re-examined not later than the
end of February, 1964.

Docking. Weardown: 2.7mm.
Screwshaft examined.

CSM Advanced.

SRL Item. The above item specially examined, ^{re-inforced} and found
to continue efficient, subject to further examination by 1.65

IT IS SUBMITTED that this vessel is eligible for the
record TS CL 1.64, subject as above with limit amended to
1.65, (12 months).



© 2021

Lloyd's Register
Foundation

012648-012953-0147

16.1.64.