

2nd June, 1961.

KOBE

8587, 8880, 924, 34, 55, 68, 71, 84,
85, 90, 91 - As recommended.

RMC 8803, 97 - As recommended.

8819 "ORIENTAL QUEEN" - As recommended, and subject also to repairs to the forward tunnel side tank (starboard side) being tested by the next Drydocking as previously recorded. I shall be glad to learn, however, if this item received attention at your port.

8689 "M.H. THAMRIN" - This ship has now been classed #100A1 "MTsf & a - Vegetable Oil" together with the appropriate notations recommended by you.

It is concluded that the diameter of the bilge suction in Nos.1,2,3, 4 and 5 holds is 80 mm. and not 50 mm. as reported, but your confirmation is desired.

8735 "TENOS" - This ship has now been classed #100A1 "MT at sides - Vegetable Oil" together with the appropriate notations recommended by you. You should furnish particulars of approval of "Starite Mostar" for rudder bearings as there does not appear to be any record of approval in this Office.

012548-012453-0201