

TANDJUNG TORAWITAN

Re Dja ltr
24/6/60

SRL (appx) to note

Insert :- "Auxiliary boiler not in service and not to be used until surveyed, safety valves adjusted and accumulation test held"

R.B. to note

Enclose aux. boiler particulars with ()

Delete record of aux. blr survey 7/59.

Advise Dja Surveyor of above and that record of ABS 7/59 should not have been assigned as ABS was not completed.



© 2021

Lloyd's Register
Foundation

013008 - 013017 - 0031