



LLOYD'S REGISTER OF SHIPPING

c/o Harrison's & Crosfield,
REC

Teromol Pos Dak. 715,

Djakarta, Indonesia

24th January 1960

Telegrams: Register, Djakarta

Reference

"TANDJUNG DATU" RPT. No.5583

"TANDJUNG RAYA" RPT. No.5633

"TANDJUNG TORAWITAN" RPT. No.5660

- DTA 9/11

Dear Sir,

The "TANDJUNG" Class vessels have two DB lubricating oil drain tanks (one forwd. and one aft.) situated under the main engine and reduction gearing, between the two longitudinal cofferdams, the capacity of these tanks is approximately 2.2 and 1.0 tons respectively.

There is also a DB oil fuel overflow tank situated at the aft. end of the foregoing mentioned cofferdams, the capacity of this tank is approximately 3.8 tons.

These small DB tanks through an oversight, have not been mentioned on the last page of the First Entry Reports 1 of the above vessels, but will be listed on the Reports 1 of the remaining three vessels.

Yours faithfully,

J.A. Boater

J.A. Boater

The Secretary,

LONDON.

(2)



© 2021

Lloyd's Register
Foundation

013008 - 013017 - 0036 1/2

013008 - 013017 - 0039

No. 5660

tee.

and
oints

& Sons,

h this

d the
d, the
of the
be
letion
for the

Society

Rpt.1
ck, the
the
of the

lating,

rivets,
ed.

ve been
ut

nd
rable).
l'

igible
ago
station

5200-013017-0035

Already mounted in RBS
noted RSB 8/2/68



© 2021

Lloyd's Register
Foundation

Reviewed by Chief
GB
SHIP'S NAME

1,500,6,59 Blk.

32