

25 SEP 1963

Ship's name *KOSEI MARU* Port *NAGASAKI* No. *1219*Last survey date *25.7.63.*Class is subject to *NIL.*

CSM advanced.

DBS due *L.63* now held.*249. / Rps.*W.D. 3.4 w/m

M/E's Nos 1, 2 & 3 crank pin upper half
 bearings (CS) found fractured at
 mating face of bearing to crank rod.
 Rps by welding and subsequent
 stress relieving carried out in order.
 at instance of Surveyor all (6) crank
 rods replaced by makers modified
spokes.

Also an additional lubricating
 oil pump fitted of 20 N³/₄ to
 increase lub oil pressure to bearings.

Surveyor states that in accordance with
 Cite No 2144, considered that ^{boiler} ~~darken~~ should
 be defected to as aux boiler. (Steam
 used for heating oil in tanks etc.)

Inst to Surveyor Part 3b 1952
 Amend No 5A dealt with
 and results found good.

PUBLICATIONS TO NOTE

db 100 lbs to be
 attached to Aux Boiler
 100 lbs.

NOTED FOR
 POSTING

It is submitted that this
 vessel is eligible for THE
 RECORD of DBS 4.63 now.

R.H.B. 24/9/63.