

LLOYD'S REGISTER OF SHIPPING

275, Chapel Street, Salford, 3, Manchester

16th October, 1959.

Telephone: Deansgate 8541

Telegrams: Lloydreg, Manchester

16.
be addressed to
YORS.

Dear Sir,

Messrs. Crossley Brothers Contract 11958.

Engine 148314.

HRN.8 Heavy Oil Propulsion Engine for

Messrs. Philip & Sons Ltd., Dartmouth.

Twin Screw Ferry for Birkenhead.

Manchester First Entry Report 100.

RECEIVED

17 OCT 1959

Ans'd.....

We have been advised by Messrs. Crossley Brothers that the above engine was damaged in transit ~~en-route~~ to Dartmouth from Messrs. Crossley Bros. Ltd., Openshaw.

This engine has now been returned to Openshaw and examined by the undersigned. The damage is not very great, and the engine will be rebuilt without any undue delay, but the third engine of this contract (total No. 4 engines) has been tested and is being sent to Dartmouth to replace the damaged engine.

Under the circumstances, we shall be glad if you will kindly return the above first entry report to enable us to re-issue.

Yours faithfully,
For the Surveyors,

2
The Secretary,
LONDON.

Lloyd's Register
Foundation
L. J. Hansel
013027-013032-0051

CLASSIFICATION

Handwritten initials

Classification Committee
Please Clerk to the

Handwritten notes and numbers

Faint, mostly illegible text, possibly bleed-through from the reverse side of the page.



© 2021

Lloyd's Register
Foundation

Faint background text, including 'TOWNS REGISTER OF SHIPPING' and 'LLOYD'S REGISTER OF SHIPPING'.

Classification
Fees app
Late att
Travellir
Special S
FEES, e
BUILD
Regis
Have the
Are the
and f
f separ
than
Have an
arran
las the
Have th
FENE
ignal
ficial
net ton
ROSS