


"PINNACLES" - Bal. Rpt.No.11651.

Refer Baltimore Surveyors' letter dated 27.7.59 regarding omission of drydocking date after survey in dry dock 4,59.

SUBMITTED the Surveyors (1) be asked if they can advance any reasons for the internal pitting in cargo tanks being now so bad as to warrant extensive wear and tear repairs to the bottom shell plating, bearing in mind that the ship carries the notation "SS 7,56(Dr)", (2) be informed it is concluded that, although the Special Survey is not due until 7,60 the repairs now recommended must, in their opinion, be dealt with before the ship is fit to continue as now classed, and (3) be requested to forward a copy of the list of contemplated classification repairs now recommended for our information and record purposes.


31.7.59.



© 2021

Lloyd's Register
Foundation

013033-013041-0099