

# Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER

1221-24 Munsey Building

Baltimore-2, Md., U. S. A.

July 27, 1959



Classn (S)

The Secretary

LONDON

RECEIVED

29 JUL 1959

Am'd ..... 31/7

Steamer "PINNACLES"  
Baltimore Rpt.No.11651

Dear Sir:

In reply to your letter of the 10th July, 1959 we wish to advise that the reason for the request that no record of Docking Survey be assigned being the Owner's intention to drydock the vessel to effect extensive wear and tear repairs to bottom shell plating (internal pitting in cargo tanks) before the vessel leaves the plant of the Maryland Shipbuilding and Drydock Company, where she is now laid up.

Yours very truly,

for the Surveyors

DHM/sb



© 2021

Lloyd's Register  
Foundation

013033-013041-0100

CLASSIFICATION

SR

H *Tom*

See Memo of  
31. 7. 59.

*[Signature]*

w/s *mm* 13/3 E9.



© 2021

Lloyd's Register  
Foundation