

to Chief Surveyors.....

Received from Chief Surveyors.....

P'S NAME "PINNACLES" REPORT Bal. No. 11651

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

re of Survey Docking: Ship examined generally ~~in~~

DS 4,59

OFFICE NOTE

-Docking brackets fitted - Bal. 5,54.

ABMP.
3.7.59.

Submitted, in this case,

the Surveyors be requested

to find out ^{from the} and advise

why a ^{dry} docking survey date
should not be assigned at
this time - refer B801 of the Rules.

© 2021

Lloyd's Register
Foundation

013033-013041-0103