

4E

11 OCT 1961

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....


SHIP'S NAME..... "ESSO 5"..... REPORT..... OSL..... No. 9361.....

Docking. Tailshaft seen.

The Surveyor states that both propeller shafts found wasted and worn in way of the bearings and new shafts satisfactorily fitted.

IT IS SUBMITTED that this vessel is eligible to remain as classed. *will peak record of TS, 761(N)*

CHECK MATERIAL OF SHAFT.



© 2021

Lloyd's Register
Foundation

9A
9.10.61.

013042 013051-0031