

013042-013051-0129

20 MAR 1959

4E

y Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME SARDINIAN.REPORT CRIMSBYNo. 24486

B.S. DUE. 12:58 now held  
 P.S. DUE 8:60 now held  
 asking for T.S.

Amend subject  
 X Screw shaft of approved  
 material and test being  
 fitted by 2:60 (12 noon)  
 JFB 1/4/59.

A Surveyor reports that a Spare (previously used)  
 screw shaft, which was found in good order, has  
 now been fitted. However from the records in this office,  
 a shaft now removed, which was fitted NEXT. 1:47/59 was  
 replace a shaft, stated to be deeply corroded at the  
 top of the cone. This is not consistent with the statement  
 above, and the Surveyor's comments are requested on  
 this point, he should to be asked to obtain from  
 the Owners some information regarding the original shaft.  
 It is also observed that in the record  
 at the top of the report 9. a  
 word of (O.G.) is shown, whereas  
 recommendation is (C.L.).  
 There is a definite date for  
 screw shaft renewal should be  
 recommended.

It is submitted that this  
 vessel is eligible for THE  
 RECORD. M.B.O. 2029

S.P.S. 2:59

T.S. record to be  
 withheld meantime JFB

X Subject to a screw shaft of approved material being fitted at the earliest opportunity.

Lloyd's Register  
 Foundation