

2

Instructions were given 19.3.25. for the character of this vessel to be withdrawn from the Register Book and three dots inserted in lieu.

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME WAR WING REPORT Gls. No. 73525

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

PERIODICAL ^(D) ~~No.~~ SPECIAL SURVEY PARTLY HELD.

When due For Reclassification When proposed to be completed --


To Complete S.S.:— See Report.

~~Portion of Survey held; &c~~

ACTION is DEFERRED for completion of Reclassification Survey.

BAM — *BAM*
25.2.49.

*Office note: - 5.44. lgs. to assign when
S.S. completed BAM.*



© 2021

Lloyd's Register
Foundation

013042-013051-0135