


"WAR WING"

Rpt. Gls. 73525

Before this case is confirmed by the COMMITTEE, IT IS
SUBMITTED the Surveyors be requested to state their recommendations
for the chain cable which is worn to the renewable diameter, also
in view of the time which the trawler has been out of class, if the
~~remainder of the~~ ^{otherwise} equipment is fully in accordance with the Rule
requirements.

IT IS FURTHER SUBMITTED the class be not reinstated until
the RECLASSIFICATION SPECIAL SURVEY is completed.

CBM.
9-2-49.
BAM



© 2021

Lloyd's Register
Foundation

013042-013051-0136