

Lloyd's Register
Foundation

If certificate is required state where to be sent.

513057-013062-0071

32 Essential Independent Pumps (Identify by position) One S.B.E.R. (bilge-ballast) *Good*
 One Port E.R. *Good*, One emergency pump in Port aft E.R. *Good*
 33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls *Good*
 34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary? *Yes, good*
 35 Fresh Water Coolers *Good* 36 Lub. Oil Coolers *Good* 37 Heaters (state service) *Good*
 38 Independent Air Compressors, Coolers & Safety Devices *Port + S.B.E.R. good*
 39 Air Receivers & Safety devices *Main Internally, good* 40 Auxiliary *Good*
 41 Oil Fuel Tanks (Not forming part of hull structure) *Internally, good*
 42 Evaporators *Good* 43 Have Evaporator Safety Valves been tested under steam? *Good*
 44 Steering Machinery *Good* 45 Windlass *Good* 46 Fire Extinguishing Arrangements *Good*

AUXILIARY ENGINES (Identify by position) One S.B. and E.R., *good*
 One Port " " " " *good*

PROPULSION		ELECTRICAL EQUIPMENT	
PORT	STARBOARD	AUXILIARY EQUIPMENT	
a Generators		1 Generators & Governors	<i>Good</i> Good
b Exciters		m Motors	<i>Good</i> "
c Air Coolers		n Switchboards & Fittings	<i>Good</i> "
d Motors		o Circuit Breakers	<i>Good</i> "
e Air Coolers		p Cables	<i>Good</i> "
f Control Gear, Cables, etc.		q Insulation Resistance	<i>Good</i> "
g Insulation Resistance		r Steering Gear Generators and Motors	<i>Good</i> "
h Insulating Oil Test		s Navigation Light Indicators	<i>Good</i> "
i Overspeed Governors			
j Magnetic Couplings			
k Air Gap			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)
 MAIN
 Superheaters
 Safety Valves
 Mountings, Doors & Fastenings
 Safety Valves Adjusted to Sat. Spt.
 Boiler Securing Arrangements
 Main Economisers
 Steam Heated Steam Generators
 Exhaust Gas Heated Economisers
 Steam Generator Safety Valves Adjusted to
 Were Oil Burning System & Remote Controls examined working in accordance with Rules?
 Forced Circulating Pumps
 Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?
 Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)
 Main
 Auxiliary (over 3 in. bore)
 Were Copper Pipes annealed?
 Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)
 Spare screwshaft No. 4450 AvH-CPM 28/4-53 with spare AvH-CPM 28/4-52 with spare
 bronze propeller Lloyd's 49134 AvH 3/4-52 now fitted
 Removed shaft now on board as spare. (No. 4449 AvH - *now on board as spare*)
 Propeller dressed up and now on board as spare.

*Boiling screwshaft renewed
 ES due 8/57 now held.*

*It is submitted that this
 vessel is eligible for THE
 RECORD. ES 7/57
 TS (CC) 26/57*

*J.E.L. am
 22/11/57*

LEAVE THIS SPACE BLANK

Survey fees ... E.S.S. Rps. 2,350.-0
 T.S.T.S. " 100 300.-0
 Damage fee ...
 Expenses...

Date when A/c rendered