

LLOYD'S REGISTER OF SHIPPING

Fondé en 1760 — Réorganisé en 1834
United with the British Corporation Register

Reconnu par la Loi sur la Sécurité de la Navigation Maritime
(Arrêté Ministériel du 5 Septembre 1908)

TÉLÉGRAMMES : LLOYDREG

TÉLÉPHONE 42.15

AFTER HOURS 878.88

202, QUAI GEORGE-V
LE HAVRE

LE HAVRE, 5th April 1961

RECEIVED

10 APR 1961

ssn (H)

Tug "ABEILLE 23 " LE HAVRE Report I0267.

Dear Sir,

This tug, now 19 years old, is only engaged in the docks area at LE HAVRE and is no longer sea-going.

At my recent examination for the Special Survey, local small areas of wastage were found on the after deck plating, and drilling was requested - giving 5m/m to 8 m/m in the thinnest parts.

At this stage of the vessel's life, the owners do not wish to renew the after deck plating as it is most probable that she will be broken up at the end of the year. If, on the other hand the tug should be sold - the matter will be placed in order as Owners' promise.

Under these circumstances, it is submitted that Owners' proposals receive sympathetic consideration and that the following entry be made in the Appendix to the Special Reasons List.

"ABEILLE 23 "- "After deck pltg locally wasted to be kept under observation ".

Yours faithfully.

Leslie S. Sims
Leslie S. SIMS.
Surveyor.

The Secretary
LONDON



© 2021

Lloyd's Register
Foundation

013103-013114-0160

CLASSIFICATION

H
KH

7/5 Nov 17/2 ss.



© 2021

Lloyd's Register
Foundation