

Chief Ship Surveyor *1/2/10.* Received from Chief Ship Surveyor  
NAME *Stl. Sc. Sug "Consort"* Rpt. *Hul* No. *22116*

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

*1st Entry.*

*It is submitted that, before this case receives the consideration of the Committee, the London Surveyors should be informed that to complete the survey the following remains to be done viz:— The top of the casing to be riveted after the machinery is fitted and the after compartment filled with water up to the height of the load line for the purpose of testing the bulkhead, also that the certificate of test of Chain cable requires to be produced and compared with the cable.*

*It is further submitted that the Superintendent of the Proving House at Lipton be requested to forward to this office the particulars of test &c of chain cable for Certificate N: 36727.*

*to Lon Surs.  
2/2/10.*

*Mr RMA  
1/2/10*



© 2021

Lloyd's Register  
Foundation