

0.2.24.

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME Stl T.S. PRINCESS ELAINE Report cls No. 47659

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

ure of Survey 1<sup>st</sup> Entry When due Revised Ruls Ruls

✠ A. I. (Steel). "With freeboard" Channel & Sound Service - Seattle and Skagway  
2 D<sup>100</sup> (Stl).

Cell D.B & E.B. 70' H25, D.T. & Ho' 2115, F.P.T. 315, A.P.T. 1325.


F.K., 7 B.H., pt Cen pt Casp, Rlyds A CP.

Promenade D<sup>k</sup> (Stl-ws)

Dr 7.3.28

7.3.28

It is enclosed the thickness of the ~~strake~~ <sup>strake</sup> below the sheerstrake at ends is as approved but the Surveyors should be requested to state if this is so. The Surveyors should also be requested to state the capacity of the emergency tanks forward.



013115-018126-0177

(Corresponding Draught

11. 1111.

... compared and found correct by

Date