

" Princess Elaine "

Fls 47659.

It is submitted that the Glasgow Surveyors be informed that in view of their recommendation, it is concluded that an oil gland has been fitted, but as they state in their report that no oil gland is fitted, they should state whether this is correct.

Lr Fls 7. 3. 28.

not fitted

S.M.

17/3/28.

J.W.D.

7/3/28

J.L.

Intermediate Shafts, diameter

as per rule
as fitted

6.7"
6 3/8"
6.83"

Thrust Shaft, diameter at collars

as per rule
as fitted

6 3/4"

Tube Shaft, diameter

013116-013124-0783