

COPY

Ship's name "ELLI"

Port

ROT.

No. 54633

Last survey date 22.9.62.

Class is subject to

indented shell plates H.11 and J.10 (s.s.f) being specially examined and dealt with as necessary, and to outer plate (p.s) (E.W.9,60) being specially examined, next drydocking.

ACTION is DEFERRED for examination in dry dock after grounding.

1.1 OCT 1962

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Docking: Damage repairs (contact and grounding) and to part of the deferred items as above.

Recommendation SUBMITTED record of DS 9 62 be assigned, subject to indented shell plates H.11 and J.10 (s.s.f) being examined and dealt with as necessary next drydocking, without other conditions.

DS 9,62 Subject without.

INSERT IN S.R.L. APPENDIX
Outer plate (p.s.) E.W. 9,60.

DELETE FROM S.R.L.
Drydocking (grounding).



© 2021

Lloyd's Register
Foundation