

13th December, 1955.

STATUS

10 - As recommended.

15 "SEVASTIK" As recommended, except that the class is subject, as previously recommended, to permanent repairs being effected to shell plates B2 and C1 (starboard side) by the next Special Survey and to bow anchor (supplied Ham.12,54) being verified with Certificate 38653 at the earliest opportunity.

12 "PANAGHIA" As recommended, except that the screwshaft record is being withheld pending its re-examination before the end of this month. It is concluded that the special condition of class regarding the propeller and sea connections may be deleted, but your confirmation is desired.



© 2021

Lloyd's Register
Foundation

013179-013185-0023