

For Class C


FREEBOARD REPORT on the "REDSHANK C"

Submitted Surveyors be advised that the Rpt CII forwarded for this vessel has been examined & found generally in order.

They should, however, be requested to report details of the manholes and covers & confirm that stretching screws are provided for the steel wires of the open rails.

D.J.N.

24.2.60

© 2021
11/3/60

noted DA 16/3/60.

Lloyd's Register
Foundation

013186-013191-0159