

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report: 26th July 41 When handed in at Local Office: 26/7/41 Port of Kobe

No. in Reg. Book: Survey held at Kobe Date, First Survey: 21/7/41 Last Survey: 24/7 1941

on the Wood, Iron or Steel M/S "AWATA MARU"

TONNAGE: Built at Nagasaki By whom Mitsubishi Jukogyo K.K. When 1937 12

GROSS 7398 Owners Nippon Yusen Kaisha Owners' Address

UNDER DK. 6551 Managers Port belonging to Tokyo

NET 4328

Surveyed Afloat or in Dry Dock? Afloat Name of Dock - Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B. All alterations in the existing records should be underlined.

Last Report, No. 11764 Port Kcb

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned to the Survey.	Machinery and Boiler Surveys (including date of N.B., in any).
*100A1 7, 3.41		*LMC 12, 37
Carrying cargo oil		*Lloyd's RMC
FP above 150°F in		4, 3.41
Deep Tanks.		DBS 11, 40
		TS(CL) 11, 38

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR DEEP TANK TEST CERTIFICATE

Deep Tank Test:-

A, B, C & D Deep Tanks were tested by a head of water to the weather deck, and upon examination the boundary bulkheads, tank top, hatches, ventilators and other connection were found sound and tight.

The double bottom tank in way of the above deep tanks was tested by a head of oil fuel to the weather deck and found sound and tight.

The heating coils in the above deep tanks were tested to twice the working pressure and found tight. Copy of certificate is attached hereto.

MANY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Plating of Decks	State if Tanks now tested	Dbng. Plates under Sounding Pipes	When put on, Month Year
Fastenings	Bulkheads	Engine Room Skylights	Boats
Plating in way of sidelights	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Books	Cement or Asphalt (State which)	Oil Bunkers	Condition, how ascertained (State if wedges removed)
Frames	Rudder	Scuppers	Sails
Radials	Steering gear and its connections	Cargo Hatchways	Equipment letter
Keelsons	Windlass	Hatches of Wood Vessels	Anchors, No. of
Stringers	Have pumps now been examined and found efficient?	Planking	Chain Locker
Inner Bottom Plating	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Cables (State if now ranged)
	Have Watertight Doors now been examined and found efficient?	Treenails ditto	length mean diam. (on board)
	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Rule length size
		Transoms Pointers, & Crutches ditto	Hawser & Warps
		Timbers of Frame at openings ditto	Standing and Running Rigging
		Ditto Ditto at other places ditto	
		Stringers, Clamps & Shelves ditto	
		Salting ditto (State if examined.)	


General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24.

Survey Fee (per Section 29)	£/s	180.00	Fees applied for, 24/7 1941
Special Damage or Repair Fee (if any) (per Sec. 29)	£		Received by me, 19
Travelling Expenses (if chargeable)	£/s	1.50	
Second Surveyor's Fee (if any)	£		

Committee's Minute As now Character Assigned

TUE. 5 MAY 1942 OMIT CLASS ON RE-PRINT.



013240-013244-0008

19824 1 NOV 1941

289

10m.11.37. Transfer Ink. (MADE IN ENGLAND.)

Is Certificate required? If so, to be sent to