

3rd September, 1958.

SOUTHAMPTON.

24988,5010 - As recommended.

25008 "ESSO WANDSWORTH" - As recommended, except that the notations
Screwshaft (N) 7,58 and Starboard Screwshaft Examined 7,58
have been assigned.

It is concluded that the 2½" diameter chain
cable placed on board has been tried over the gypsies and found
to be in order.

24993 "BELGRAVE" - As recommended. Postponement of the Special
Survey until the end of September, 1959 has been approved, and
I shall be glad if you will inform the Owners accordingly.

013260-013267-0112

© 2021
Lloyd's Register
Foundation