

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
                          Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

9th September, 1966

C.  
CGB/BN

Dear Sirs,

M.S. "MONSUN"

The Reports of the surveys held at Hamburg and at Gothenburg in June have now received the consideration of the Committee and a fresh record of Docking Survey 6.66 has been assigned.

As a result of these surveys, the class has been continued subject as follows:-

(1) The welding of the Main Engine A frames stiffening plates between units Nos.4,5,6 & 7 forward and Nos.8 & 9 forward and aft being re-examined before the end of December 1966.

(2) The starboard boiler, in which some tube leakage was dealt with by plugging, being again examined under full pressure before the end of the present month.

I shall be glad if you will inform the Owners accordingly.

To complete the Auxiliary Boiler Survey for a fresh record of ABS 6.66, the qualification of class item No.2 requires to be dealt with, and the exhaust gas economiser requires to be surveyed



Continued.....

© 2021

Lloyd's Register  
Foundation

013284-013292-0218 1/2

(2)

and its safety valves adjusted. I shall be glad to learn what arrangements the Owners propose to make in this respect.

Yours faithfully,

pro Classification Manager,

The Surveyors,  
HELSINGFORS.



© 2021

Lloyd's Register  
Foundation

0218 2/2