

COPY

# LLOYD'S REGISTER OF SHIPPING



Port ..... H a m b u r g .....  
Date ..... 1st July, 1966 .....

**This is to Certify** *that I have*

*surveyed the* **M.S. "MONSUN" 10729** *gross tons of* **Helsingfors**  
*whilst in drydock and afloat at Messrs. Deutsche Werft A.G.,*  
**Hamburg, Reihertstieg, on the 5th June, 1966 and subsequently**  
*to the 22nd June, 1966 on account of* **Damage, (see Overleaf)**  
*and Docking*

**p. t. o.**

*and that I am transmitting to the Committee of Lloyd's Register of*  
*Shipping, London, a report, stating that all repairs recommended by*  
*me have been completed to my satisfaction, also that I am*

*recommending that she be* **retained as now classed in the Register**  
**Book with fresh record of drydocking 6.66 without condition**  
*regarding set in sole, shell plating with internals and bulwark*  
*stiffeners and adjacent sheerstrake plating (ss) but subject to*  
*any other outstanding condition which may at present be attached*  
*to the ship's class being dealt with as previously recommended.*

*Rolf Rudolph*  
.....  
*Surveyor to Lloyd's Register of Shipping*

**KEY TO ABBREVIATIONS**

AS Annual Survey  
BiS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
CSH Hull Special Survey (Continuous)


This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society."

N. Cert. B 240,m,9,65 (MADE AND PRINTED IN ENGLAND.)

013284-013292-0226

LLOYD'S REGISTER OF SHIPPING



Damage stated to have been caused through heavy weather on voyage from Bombay to New York between the 26th and 27th January, 1966.

- a) damage situated on sideshell plating (ss) on H, J, L, and M- strake frs. Nos. 94-107
- b) damage situated at forward bulwark on bridge deck (p.s.)
- c) damage situated on forward poopdeck (s.e.) and adjacent bulwark

This is a copy of the original report.

Gross tons

Surveyed the

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be

*[Handwritten signature]*  
 Director of Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

- SS - Hull Shell Plating
- PS - Hull Deck Plating
- SM - Hull Shell Plating (Mild Steel)
- CS - Hull Shell Plating (Carbon Steel)

